# Weathertzeiton Assistance

## Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/20002BR-0119/1

Work Order Type: Weatherization

Audit Name: 20002BR-0119AUDIT

#### **CLIENT INFORMATION**

Client ID: 20002BR-0119

#### <u>AGENCY INFORMATION</u>

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

**Address:** 155 Sixth Street SE **Fax:** (423) 479-4113

Agency Contact: Bloodworth, William D. Work Phone:

**Cell Phone:** (423) 505-4585

Email Address: Darblood@comcast.net

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

Site Built Built approx 1985 with addition built approx 2000 Approx 2189 sqft

Client ID: 20002BR-0119

### Measures

	dercut doors to achieve pa differential	less than		Componen	its			Inspected	
betwee	cut the following doors to a en door and flooring. Laun n (2 doors), Bedroom in a	dry room,	Exercis	se room, Ba	throom in ter bedro	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
0 Labor	Undercut door	Each	7			<i>y</i>			
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Measure 2 DW	re 2 DWH Pipe Insulation			Componer	ıts	Inspected			
			Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	DHW Pipe Insulation	Linear Foot	4						
2 Labor	DHW Pipe Insulation	Each	1						
3 Other	DHW Pipe Insulation	Each	1						
Other Detail						1			
						]			
	Measure Sub Total:					Sub Total:			
Field Notes:									

Measure 3 Floor Ins. R-19 Comment			Components Main Crawlspace					Inspected	
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1549						
Other Detail						1			
		Measure Sub Total:				Sub Total:			
	all Bathroom Exhaust F	-an		Componen	ts			Inspected	
Comment Vent Ur	nit to the Exterior		Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Health and Safety     Items	Bathroom exhaust fan	Each	3						
2 Labor	Labor	Each	3						
Other Detail									
			Measure	e Sub Total:		,	Sub Total:		
Field Notes:									
		Work Or	der Gra	nd Total:		Gran	d Total:		

Report Run On: 5/19/2010